

SECURITY ALERT WIND ESCAPETTOR

RESCUE DESCENDER AND PARTNER COMPLEMENT



We have detected that when the following conditions are met at the same time:

1. There is an overload in the equipment.
2. An excessively strong actuation of the lever is carried out.

The Wind Escapettor rescue descender can damage the rope, even severing it due to the aggressiveness of the anti-panic cam tooth of some equipment.

This problem has been identified in the devices with the serial number starting by 20.05 and 20.02

These circumstances of unforeseen use, in which the rope can be damaged, are exceptional and do not correspond to the usual use of the equipment, nor to those contemplated in the tests carried out for its approval.

At Protection we are committed to always offering the client maximum security. By following this policy, we believe that even improper use should not lead to risks for the user.

– **IF YOU HAVE A WIND ESCAPETTOR RESCUE DESCENDER:**



- Use the equipment according to the manufacturer's instructions.
- Send it to review as soon as possible

– **IF YOU HAVE A PARTNER COMPLEMENT:**



- Stop using it immediately until your Wind Escapettor equipment is reviewed.

Protection or your authorized dealer will contact you to indicate the steps to follow.

If you wish, you can contact Protection at the email admon@protection.com or by calling +34 946 534 236

This alert does not affect the Escapettor Rescue Descender.

Arrate Juanes Oñate

Arrate Juanes Oñate
Company Director