

January 24, 2014

Product Inspection Notice: **Immediate Action Required**

PRODUCT(S): Rebar Swivel Hook. Part numbers 01600, 01603, 01608, & 01611

Please be advised that Guardian Fall Protection SKU numbers #01600, #01603, #01608 & #01611 use a Usang Industrial Co., Ltd. Rebar Swivel Hook.

Usang has notified Guardian Fall Protection and numerous other Fall Protection manufacturers in the United States of an inspection notice pertaining to one of their products, the Rebar Swivel Hook S-3616.

This product, supplied by Usang, has a threaded bolt assembly that connects the swivel element to the rebar snap hook. If this bolt assembly is damaged as indicated in the inspection notice below, it may not function properly.

We are strongly urging all customers to inspect their rebar swivel hooks per the inspection notice. This is not a recall.

Please read the following instructions thoroughly, as they will explain in detail how to properly inspect the swivel rebar hook.

If you have any questions, please contact David Gambini at DavidG@guardianfall.com or at **1.800.466.6385 ext. 144.**

Phone: (800) 466.6385

Fax: (800) 670.7892

Web: www.guardianfall.com

Address: 6305 South 231st Street Kent, WA 98032


YOUR SAFETY COMPANY FOR LIFE

GUARDIAN
FALL PROTECTION
PERFORMANCE SAFETY GEAR

! "###

\$
\$
%&' \$ _____
(\$ _____
) *

> 2 0 + +& # " &) " "



?)

) *